



January 20, 2026

E-mail: MMoral23@calstatela.edu

Mr. Mike Morales
Risk Management
Environmental Health & Safety
California State University Los Angeles (CSULA)
5151 State University Dr.
Los Angeles, CA 90032

Re: Asbestos Ambient Air Testing
King Hall
Basement – 5th Floor
5151 State University Dr.
Los Angeles, CA 90032

GETC Project No.: **E226-024**


Dear Mr. Morales:

Global Environmental Training & Consulting (GETC) performed ambient air testing for asbestos for the above referenced property at your request. Samples were taken to determine ambient exposure levels within King Hall – Basement – 5th Floor.

Ambient Air Samples were collected from several areas throughout King Hall (See diagram for locations). All samples were analyzed using Transmission Electron Microscopy (TEM) using the Asbestos Hazard Emergency Response Act (AHERA) Method which determines specific asbestos structure concentration. A total of twenty-one (21) ambient air samples were taken throughout the building. Twenty (20) air samples concluded No Asbestos Structures Detected. Only one (1) air sample from the Besement identified one (1) structure. The air sample is below the EPA Clearance Criteria of ≤ 70 structures/millimeter squared (s/mm^2). Building is approved for occupancy.

Thank you for choosing GETC as the consultant for this project. If you have any questions, please do not hesitate to contact our office at (626) 962-4436.

Respectfully submitted,
Global Environmental Training & Consulting, Inc.


Mario Virgen
President, CAC

Air / Sampling / Results

SAMPLE №	ACTIVITY CODE	DESCRIPTION / LOCATION	TYPE OF ASBESTOS
A-01	TEM	Basement – B Wing	NSD
A-02	TEM	Basement – C Wing	NSD
A-03	TEM	Basement – C Wing	ONE (1) CHRYSOTILE STRUCTURE
A-04	TEM	Basement – D Wing	NSD
A-05	TEM	5th Floor – B Wing	NSD
A-06	TEM	5th Floor – C Wing	NSD
A-07	TEM	4th Floor – B Wing	NSD
A-08	TEM	4th Floor – C Wing	NSD
A-09	TEM	4th Floor – D Wing	NSD
A-10	TEM	3rd Floor – B Wing	NSD
A-11	TEM	3rd Floor – C Wing	NSD
A-12	TEM	3rd Floor – D Wing	NSD
A-13	TEM	3rd Floor – A Wing	NSD
A-14	TEM	1st Floor – D Wing	NSD
A-15	TEM	1st Floor – B Wing	NSD
A-16	TEM	1st Floor – C Wing	NSD
A-17	TEM	1st Floor – Suite 1064	NSD
A-18	TEM	2nd Floor – C Wing	NSD
A-19	TEM	2nd Floor – B Wing	NSD
A-20	TEM	2nd Floor – D Wing	NSD
A-21	TEM	2nd Floor – A Wing	NSD
A-22	FB	Field Blank	NSD

NOTES:

NSD = NO STRUCTURES DETECTED

SAMPLING TABLE

CONTACT INFORMATION		PROJECT INFORMATION		TURN AROUND TIME CODES (TAT)	
Company: Glossal Environmental Training & Consulting	Address: 1520 W. Cameron Ave Suite 103 West Covina, CA 91790	Project ID: E226-024	Sample ID: 90032	STD – Standard (DEFAULT)	Rushes received after 2pm or on weekends, will be considered received the next business day. Please alert us in advance of weekend analysis needs.
Contact: Mario Virgen / Miguel Virgen	Sampling Date & Time: 01/17/26 0515	Project Description: KING HALL	Sampled By: Sergio Perez Rashad Perez	ND – Next Business Day	
Phone: 626-962-4436	Special Instructions: EMAIL RESULTS TO: STAFF@GLOBALENVIROTRAINING.COM, MARIO.VIRGEN@GLOBALENVIROTRAINING.COM, MIGUEL.VIRGEN@GLOBALENVIROTRAINING.COM			SD – Same Business Day Rush*	
				*Please call Client Services for locations with Rush services	
Sample ID	Description	Sample Type (Below)	TAT (Above)	Total Volume (Air Samples only)	Notes
A-01	Basement South Hallway	A	SD	1,287 liters	
A-02	Main				
A-03	East				
A-04	North				
A-05	5th Floor				
A-06	4th Floor				
A-07	South				
A-08	East				
A-09	South				
A-10	North				
A-11	South				
	East				

SAMPLE TYPE CODES	RELINQUISHED BY	DATE & TIME	RECEIVED BY	DATE & TIME
A - Air	W - Wipe	01/19/26	Sergio Perez	01/19/26
B - Bulk	T - Tape		Sergio Perez	
D - Dust	R - Rock			
SO - Soil	O - Other			

By submitting this Chain of Custody, you agree to be bound by the terms and conditions set forth at: <https://www.eurofinsus.com/environment-testing/built-environment-testing>

Copyright © 2022 Eurofins EPK Built Environment Testing, LLC



East: (866) 871-1984
Central: (800) 651-4802
West: (866) 888-6653

931 Corporate Center Dr.
Pomona, CA 91768

004380465

ASBESTOS ANALYSIS

REQUESTED SERVICES (Check boxes below)

PCM Air	PLM		Rock & Soil	Other Requests
	Bulk	PCM		
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Asbestos TEM - AHERA
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Lead Analysis - Flame AA - LEAD WIPES
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	CARB 435 Method (1000 Point Count)
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	CARB 435 Method (400 Point Count)
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Gravimetric Point Count (1000 Pt Count)
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Gravimetric Point Count (400 Pt Count)
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	EPA Point Count (400 Point Count)
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	EPA Point Count (200 Point Count)
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Asbestos Bulk PLM
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OSHA with TWA
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Fiber Count (NIOSH 7400)

CONTACT INFORMATION

Company: **Global Environmental Training & Consulting**
Address: **1520 W. Cameron Ave Suite 103
West Covina, CA 91790**
Contact: **Mario Virgen / Miguel Virgen**
Phone: **626-962-4436**
Special Instructions:
EMAIL RESULTS TO: STAFF@GLOBALENVIROTRAINING.COM,
MARIO.VIRGEN@GLOBALENVIROTRAINING.COM,
MIGUEL.VIRGEN@GLOBALENVIROTRAINING.COM

PROJECT INFORMATION

Project ID	TURN AROUND TIME CODES (TAT)		
Project Description:	STD - Standard (DEFAULT)	ND - Next Business Day	Rush received after 2pm or on weekends, will be considered received the next business day. Please alert us in advance of weekend analysis needs.
Project Zip Code:	SD - Same Business Day Rush*	SD - Same Business Day Rush*	
PO Number:	Sergio Perez Rashad Rees	*Please call Client Services for locations with Rush services	
Sample ID	Description	Sample Type (Below)	TAT (Above) Total Volume (Air Samples only)
A-12	3rd Floor North Hallway	A	SD 1,287 liters
A-13	West		
A-14	1st Floor North		
A-15	South		
A-16	East		
A-17	Suite 1064		
A-18	2nd Floor East Hallway		
A-19	South		
A-20	North		
A-21	West		
A-22	Field Blank		Do Not Analyze

SAMPLE TYPE CODES	RELINQUISHED BY	DATE & TIME	RECEIVED BY	DATE & TIME
A - Air	W - Wipe	01/19/26	Sergio Perez	1/19/26
B - Bulk	T - Tape	07/15	Sergio Perez	07/15
D - Dust	R - Rock			
SO - Soil	O - Other			

By submitting this Chain of Custody, you agree to be bound by the terms and conditions set forth at: <https://www.eurofinsus.com/environment-testing/built-environment-testing/resources/sampling-guides-and-forms/>

Copyright © 2022 Eurofins EPK Built Environment Testing, LLC

ANALYTICAL LABORATORY REPORT

Report for:

Mario Virgen
Global Environmental Training & Consulting, Inc.
1520 W. Cameron Ave
Suite 103
West Covina, CA 91790

Regarding: Eurofins Built Environment Testing West, LLC
Project: E226-024; KING HALL
EML ID: 4380465

Approved by:



Approved Signatory
Arthur Bucio

Dates of Analysis:
Asbestos TEM - AHERA (40CFR Part 763, Subpart E, Appendix A): 01-19-2026

Service SOPs: Asbestos TEM - AHERA (40CFR Part 763, Subpart E, Appendix A) (EBET-TEM-SOP83945)
NVLAP Lab Code 200757-0

All samples were received in acceptable condition unless noted in the Report Comments portion in the body of the report. Due to the nature of the analyses performed, field blank correction of results is not applied. The results relate only to the samples as received and tested.

Eurofins Built Environment Testing West, LLC ("the Company"), a member of the Eurofins Built Environment Testing group of companies, shall have no liability to the client or the client's customer with respect to decisions or recommendations made, actions taken or courses of conduct implemented by either the client or the client's customer as a result of or based upon the Test Results. In no event shall the Company be liable to the client with respect to the Test Results except for the Company's own willful misconduct or gross negligence nor shall the Company be liable for incidental or consequential damages or lost profits or revenues to the fullest extent such liability may be disclaimed by law, even if the Company has been advised of the possibility of such damages, lost profits or lost revenues. In no event shall the Company's liability with respect to the Test Results exceed the amount paid to the Company by the client therefor.

Eurofins Built Environment Testing West, LLC

2841 Dow Avenue, Suite 300, Tustin, CA 92780

(833) 465-5857 www.eurofinsus.com/Built

Client: Global Environmental Training & Consulting, Inc.

C/O: Mario Virgen
Re: E226-024; KING HALL

Date of Sampling: 01-17-2026

Date of Receipt: 01-19-2026

Date of Report: 01-19-2026

ASBESTOS TEM AHERA REPORT

Lab ID-Version‡ Location Analysis Date	Volume (liters)	Area Analyzed (mm ²)	Grid Openings Examined	Analytical Sensitivity (S/cm ³)	Non- Asbestos Count	Asbestos Types	Asbestos Structures (S)		§Asbestos Concentration	
							>= 5µm	>=0.5-<5µm	S/mm ²	S/cm ³
21957707-1 A-01 Basement South Hallway 01/19/2026	1287	0.06	6	0.005	0	No Structures Detected	0	0	<15.723	<0.005
Comments:										
21957708-1 A-02 Basement Main Hallway 01/19/2026	1287	0.06	6	0.005	0	No Structures Detected	0	0	<15.723	<0.005
Comments:										
21957709-1 A-03 Basement East Hallway 01/19/2026	1287	0.06	6	0.005	0	Chrysotile	0	1	15.723	0.005
Comments:										
21957710-1 A-04 Basement North Hallway 01/19/2026	1287	0.06	6	0.005	1	No Structures Detected	0	0	<15.723	<0.005
Comments:										
21957711-1 A-05 5th Floor South Hallway 01/19/2026	1287	0.06	6	0.005	0	No Structures Detected	0	0	<15.723	<0.005
Comments:										
21957712-1 A-06 5th Floor East Hallway 01/19/2026	1287	0.06	6	0.005	0	No Structures Detected	0	0	<15.723	<0.005
Comments:										

§ Asbestos Concentration has been rounded to three significant figures to reflect analytical precision.

The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government.

Digital images of diffraction patterns and copies of analytical bench sheets pertaining to this project are available upon request. The estimated measurement of uncertainty and 95% confidence interval for the test results are also available upon request.

The laboratory is not responsible for data collected by personnel who are not part of the laboratory. Results reported in both structures/cm³ and structures/mm² are dependent on the volume of air sampled and measured by non-laboratory personnel.

‡ A "Version" indicated by "-x" after the Lab ID# with a value greater than 1 indicates a sample with amended data. The revision number is reflected by the value of "x".

Client: Global Environmental Training & Consulting, Inc.
C/O: Mario Virgen
Re: E226-024; KING HALL

Eurofins Built Environment Testing West, LLC

2841 Dow Avenue, Suite 300, Tustin, CA 92780
(833) 465-5857 www.eurofinsus.com/Built

Date of Sampling: 01-17-2026
Date of Receipt: 01-19-2026
Date of Report: 01-19-2026

ASBESTOS TEM AHERA REPORT

Lab ID-Version‡ Location Analysis Date	Volume (liters)	Area Analyzed (mm ²)	Grid Openings Examined	Analytical Sensitivity (S/cm ³)	Non- Asbestos Count	Asbestos Types	Asbestos Structures (S)		§Asbestos Concentration	
							>= 5µm	>=0.5-<5µm	S/mm ²	S/cm ³
21957713-1 A-07 4th Floor South Hallway 01/19/2026	1287	0.06	6	0.005	0	No Structures Detected	0	0	<15.723	<0.005
Comments:										
21957714-1 A-08 4th Floor East Hallway 01/19/2026	1287	0.06	6	0.005	0	No Structures Detected	0	0	<15.723	<0.005
Comments:										
21957715-1 A-09 4th Floor North Hallway 01/19/2026	1287	0.06	6	0.005	0	No Structures Detected	0	0	<15.723	<0.005
Comments:										
21957716-1 A-10 3rd Floor South Hallway 01/19/2026	1287	0.06	6	0.005	0	No Structures Detected	0	0	<15.723	<0.005
Comments:										
21957717-1 A-11 3rd Floor East Hallway 01/19/2026	1287	0.06	6	0.005	0	No Structures Detected	0	0	<15.723	<0.005
Comments:										
21957718-1 A-12 3rd Floor North Hallway 01/19/2026	1287	0.06	6	0.005	0	No Structures Detected	0	0	<15.723	<0.005
Comments:										

§ Asbestos Concentration has been rounded to three significant figures to reflect analytical precision.

The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government.

Digital images of diffraction patterns and copies of analytical bench sheets pertaining to this project are available upon request. The estimated measurement of uncertainty and 95% confidence interval for the test results are also available upon request.

The laboratory is not responsible for data collected by personnel who are not part of the laboratory. Results reported in both structures/cm³ and structures/mm² are dependent on the volume of air sampled and measured by non-laboratory personnel.

‡ A "Version" indicated by "-x" after the Lab ID# with a value greater than 1 indicates a sample with amended data. The revision number is reflected by the value of "x".

Eurofins Built Environment Testing West, LLC

2841 Dow Avenue, Suite 300, Tustin, CA 92780

(833) 465-5857 www.eurofinsus.com/BuiltClient: Global Environmental Training & Consulting,
Inc.C/O: Mario Virgen
Re: E226-024; KING HALL

Date of Sampling: 01-17-2026

Date of Receipt: 01-19-2026

Date of Report: 01-19-2026

ASBESTOS TEM AHERA REPORT

Lab ID-Version‡ Location Analysis Date	Volume (liters)	Area Analyzed (mm ²)	Grid Openings Examined	Analytical Sensitivity (S/cm ³)	Non- Asbestos Count	Asbestos Types	Asbestos Structures (S)		§Asbestos Concentration	
							>= 5µm	>=0.5-<5µm	S/mm ²	S/cm ³
21957719-1 A-13 3rd Floor West Hallway 01/19/2026	1287	0.06	6	0.005	0	No Structures Detected	0	0	<15.723	<0.005
Comments:										
21957720-1 A-14 1st Floor North Hallway 01/19/2026	1287	0.06	6	0.005	0	No Structures Detected	0	0	<15.723	<0.005
Comments:										
21957721-1 A-15 1st Floor South Hallway 01/19/2026	1287	0.06	6	0.005	0	No Structures Detected	0	0	<15.723	<0.005
Comments:										
21957722-1 A-16 1st Floor East Hallway 01/19/2026	1287	0.06	6	0.005	0	No Structures Detected	0	0	<15.723	<0.005
Comments:										
21957723-1 A-17 1st Floor Suite 1064 01/19/2026	1287	0.06	6	0.005	0	No Structures Detected	0	0	<15.723	<0.005
Comments:										
21957724-1 A-18 2nd Floor East Hallway 01/19/2026	1287	0.06	6	0.005	0	No Structures Detected	0	0	<15.723	<0.005
Comments:										

§ Asbestos Concentration has been rounded to three significant figures to reflect analytical precision.

The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government.

Digital images of diffraction patterns and copies of analytical bench sheets pertaining to this project are available upon request. The estimated measurement of uncertainty and 95% confidence interval for the test results are also available upon request.

The laboratory is not responsible for data collected by personnel who are not part of the laboratory. Results reported in both structures/cm³ and structures/mm² are dependent on the volume of air sampled and measured by non-laboratory personnel.

‡ A "Version" indicated by "-x" after the Lab ID# with a value greater than 1 indicates a sample with amended data. The revision number is reflected by the value of "x".

Eurofins Built Environment Testing West, LLC

2841 Dow Avenue, Suite 300, Tustin, CA 92780

(833) 465-5857 www.eurofinsus.com/BuiltClient: Global Environmental Training & Consulting,
Inc.C/O: Mario Virgen
Re: E226-024; KING HALLDate of Sampling: 01-17-2026
Date of Receipt: 01-19-2026
Date of Report: 01-19-2026**ASBESTOS TEM AHERA REPORT**

Lab ID-Version‡ Location Analysis Date	Volume (liters)	Area Analyzed (mm ²)	Grid Openings Examined	Analytical Sensitivity (S/cm ³)	Non- Asbestos Count	Asbestos Types	Asbestos Structures (S)		§Asbestos Concentration	
							>= 5µm	>=0.5-<5µm	S/mm ²	S/cm ³
21957725-1 A-19 2nd Floor South Hallway 01/19/2026	1287	0.06	6	0.005	0	No Structures Detected	0	0	<15.723	<0.005
Comments:										
21957726-1 A-20 2nd Floor North Hallway 01/19/2026	1287	0.06	6	0.005	0	No Structures Detected	0	0	<15.723	<0.005
Comments:										
21957727-1 A-21 2nd Floor West Hallway 01/19/2026	1287	0.06	6	0.005	0	No Structures Detected	0	0	<15.723	<0.005
Comments:										

§ Asbestos Concentration has been rounded to three significant figures to reflect analytical precision.

The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government.

Digital images of diffraction patterns and copies of analytical bench sheets pertaining to this project are available upon request. The estimated measurement of uncertainty and 95% confidence interval for the test results are also available upon request.

The laboratory is not responsible for data collected by personnel who are not part of the laboratory. Results reported in both structures/cm³ and structures/mm² are dependent on the volume of air sampled and measured by non-laboratory personnel.

‡ A "Version" indicated by "-x" after the Lab ID# with a value greater than 1 indicates a sample with amended data. The revision number is reflected by the value of "x".

Client: Global Environmental Training & Consulting,
Inc.
C/O: Mario Virgen
Re: E226-024; KING HALL

Eurofins Built Environment Testing West, LLC
2841 Dow Avenue, Suite 300, Tustin, CA 92780
(833) 465-5857 www.eurofinsus.com/Built

Date of Sampling: 01-17-2026
Date of Receipt: 01-19-2026
Date of Report: 01-19-2026

ASBESTOS TEM AHERA REPORT
PROJECT ANALYSTS AND SIGNATORY REPORT

Project Analysts



Analyst: Arthur Bucio




Analyst: Yue Wu


The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government. The Company reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.


‡ A "Version" indicated by -"x" after the Lab ID# with a value greater than 1 indicates a sample with amended data. The revision number is reflected by the value of "x".

SCHEMATIC




FIFTH FLOOR







MARTIN LUTHER KING HALL

THIRD FLOOR







INSPECTOR'S CERTIFICATION

Project No. **E226-024**

State of California
Division of Occupational Safety and Health
Certified Site Surveillance Technician
Sergio R Perez-Loa



Name _____
Certification No. **18-6224**
Expires on **05/15/2026**

This certification was issued by the Division of
Occupational Safety and Health as authorized
by Sections 7180 et seq of the Business and
Professions Code.



State of California
Division of Occupational Safety and Health
Certified Asbestos Consultant
Mario A Virgin



Name _____
Certification No. **00-2859**
Expires on **01/05/2027**

This certification was issued by the Division of
Occupational Safety and Health as authorized
by Sections 7180 et seq of the Business and
Professions Code.

