

South Coast Air Quality Management District

21865 Copley Drive, Diamond Bar, CA 91765-4182
Phone: (909) 396-2336
www.aqmd.gov

Notification Number
515827

Rule 1403 Notification of Procedure 1 Asbestos Removal

Please maintain a copy of this Notification at the job site, either electronic or paper.

Project Type

Project Type	Asbestos Removal	Project Urgency	Routine
Completed By	Karla Echeverria	Phone Number	(562) 941-1434

Contractor Information

Company Name	QUALITY ENVIRONMENTAL, INC.	Address	13123 LAKELAND RD
City	SANTA FE SPRINGS	State	CA
Zip	90670		
CSLB License #	876494	OSHA REG #	947
Supervisor #1	Luis Caballero	Phone	(562) 686-6454
Supervisor #2	Antonio Rangel	Phone	(562) 328-0459
Supervisor #3	Erick Marin	Phone	(562) 212-5250

Site Information

Site Name	CSULA	Project #	5185
Site Street #	5151	Street Name	State University Dr
Cross Street	Paseo Rancho Castilla	Site County	Los Angeles
City	Los Angeles	State	CA
Zip	90032		

Site Owner	California State University Los Angeles	Owner Address	5151 State University Dr
City	Los Angeles	State	CA
Zip	90032		

Project Start Date	6/14/2018	Project End Date	6/29/2018
Project Work Shift(s)	Day	Building Size in Sq.ft	65000
Number of Floors	4	Building Age (years)	70
Number of Building/Dwelling Units	1	Building Prior Use	University/College
Asbestos Survey	Yes	Asbestos Found	Yes
Asbestos Removed	No	Building to be Demolished	No
Describe Work	Removal and disposal of ACM floor tiles	Describe Work Location	King Hall, Music, Fine Arts

Project Information

Asbestos Information

Amount of Asbestos in each type in Sq.Ft

Acoustic Ceiling	0	Linoleum	0	Insulation	0	Fire Proofing	0
Ducting	0	Dry Wall	0	Mastic (Non-friable)	115	Floor Tiles (Non-friable)	0
Transite	45	Roofing	0	Stucco	0	Plaster	0

Other (friable)	0	Coal Tar Wrap	0	Mastic (Friable)	740	Floor Tile (Friable)	740
Other (non-friable)	0						

Asbestos Amount to be Removed in Sq.Ft

FRIABLE	1480
CLASS I	160
CLASS II	0
Total	1640

Asbestos Removal From	Surfaces	Control Procedures	1
Asbestos Detection Procedure(s)	Survey , Bulk Sampling , Inspection		

Waste Information

Waste Transporter	EARTHWISE SERVICES, LLC		
Address	5949 DODD STREET	City	MIRA LOMA
State	CA	Zip	91752
Landfill	Azusa Land Reclamation		
Address	1211 W Gladstone St	City	Azusa
State	CA	Zip	91702

Fee Payment

Total Amount of Asbestos to be Removed in sq.ft	1640
Project Size Fee	186.07
Additional Fee	0
Total Fee	\$ 186.07
Payment Made	\$ 186.07
Balance Due	\$ 0

By clicking the Sign & Submit button, I certify that an individual trained in the provisions of SCAQMD Rule 1403 and the Asbestos NESHAP (CFR Title 40, Part 61, Subpart M) will be onsite during the demolition or renovation and evidence that the required training has been accomplished by this person will be available for inspection during normal business hours. In addition, I certify that all of the information contained herein and information submitted with this Notification is true and correct.