

South Coast Air Quality Management District

21865 Copley Drive, Diamond Bar, CA 91765-4182
Phone: (909) 396-2336
www.aqmd.gov

Notification Number
523894

Rule 1403 Notification of Emergency Procedure 1 Asbestos Removal

Please maintain a copy of this Notification at the job site, either electronic or paper.

Project Type

Project Type	Asbestos Removal	Project Urgency	Emergency
Completed By	Karla Echeverria	Phone Number	(562) 941-1434

Contractor Information

Company Name	QUALITY ENVIRONMENTAL, INC.	Address	13123 LAKELAND RD
City	SANTA FE SPRINGS	State	CA
Zip	90670		
CSLB License #	876494	OSHA REG #	947
Supervisor #1	Luis Caballero	Phone	(562) 686-6454
Supervisor #2	David De Jesus	Phone	(562) 212-3268
Supervisor #3	Erick Marin	Phone	(562) 212-5250

Site Information

Site Name	CSULA King Hall	Project #	5261
Site Street #	5151	Street Name	STATE UNIVERSITY DR
Cross Street	Paseo Rancho Castilla	Site County	Los Angeles
City	Los Angeles	State	CA
Zip	90032		
Contact Name	Gerald Miers	Contact Phone	(323)312-9670

Site Owner	California State University Los Angeles	Owner Address	5151 STATE UNIVERSITY DR
City	Los Angeles	State	CA
Zip	90032		

Project Start Date	8/3/2018	Project End Date	8/6/2018
Project Work Shift(s)	Night	Building Size in Sq.ft	65000
Number of Floors	4	Building Age (years)	70
Number of Building/Dwelling Units	9	Building Prior Use	School
Asbestos Survey	Yes	Asbestos Found	Yes
Asbestos Removed	No	Building to be Demolished	No
Describe Work	Removal and disposal of ACM floor tiles,carpet and mastic	Describe Work Location	King Hall Room D150

Project Information

Asbestos Information

Amount of Asbestos in each type in Sq.Ft

Acoustic Ceiling	0	Linoleum	0	Insulation	0	Fire Proofing	0
Ducting	0	Dry Wall	0	Mastic (Non-friable)	0	Floor Tiles (Non-friable)	0

Transite	0	Roofing	0	Stucco	0	Plaster	0
Other (friable)	0	Coal Tar Wrap	0	Mastic (Friable)	240	Floor Tile (Friable)	240
Other (non-friable)	240						

Asbestos Amount to be Removed in Sq.Ft

FRIABLE	480
CLASS I	240
CLASS II	0
Total	720

Asbestos Removal From	Surfaces	Control Procedures	1
Asbestos Detection Procedure(s)	Survey , Bulk Sampling , Inspection		

Emergency

Sudden Unexpected Event(s)	Health/Safety		
Name of Person/Declaring Authorizing the Emergency	Gerald Miers	Phone	(323)312-9670
Date of Emergency	7/31/2018		

Waste Information

Waste Transporter	EARTHWISE SERVICES, LLC		
Address	5949 DODD STREET	City	MIRA LOMA
State	CA	Zip	91752
Landfill	Azusa Land Reclamation		
Address	1211 W Gladstone St	City	Azusa
State	CA	Zip	91702

Fee Payment

Total Amount of Asbestos to be Removed in sq.ft	720
Tracking Number	3321917
Project Size Fee	62.92
Additional Fee	62.92
Total Fee	\$ 125.84
Payment Made	\$ 125.84
Balance Due	\$ 0

By clicking the Sign & Submit button, I certify that an individual trained in the provisions of SCAQMD Rule 1403 and the Asbestos NESHAP (CFR Title 40, Part 61, Subpart M) will be onsite during the demolition or renovation and evidence that the required training has been accomplished by this person will be available for inspection during normal business hours. In addition, I certify that all of the information contained herein and information submitted with this Notification is true and correct.